

# Harness inspection certificate - EN

 Inspection certificate number: **PH\_372.2022**

 Impact pad number: **MISC\_236.2022**

## Manufacturer data

**Manufacturer name:** DLCO  
**Representative:** Thomas Bourdeau  
**Street:** Le villaret  
**Post code / place:** 05120 ST MARTIN DE QUEYRIERES  
**Country:** France

Sample data:	Harness	Impact pad
--------------	---------	------------

<b>Name:</b>	<b>Grasshopper Mk2</b>	<b>Name Impact pad: <sup>(1)</sup></b>	<b>AirPillow</b>
<b>Type:</b>	<b>ABS</b>	<b>Impact pad integrated: <sup>(1)</sup></b>	<b>No</b>
<b>Size:</b>	<b>L</b>	<b>Impact pad type:</b>	<b>Inflatable</b>
<b>Weight of Sample [kg]:</b>	<b>2.81</b>	<b>Weight of Sample [kg]: <sup>(1)</sup></b>	<b>0.32</b>
<b>Serial number:</b>	<b>Proto#1</b>	<b>Serial number:<sup>(1)</sup></b>	<b>165C210</b>
<b>Clip-in weight [kg]:</b>	<b>100</b>	<b>Date of reception:</b>	<b>10.08.2022</b>
<b>Integrated container for rescue system:</b>	<b>Yes</b>		
<b>Volume container [cm<sup>3</sup>]:</b>			
			<b>4000 max</b>
			<b>2500 min</b>
<b>Date of reception:</b>	<b>24.01.2022</b>		

Test report summary	Structual test	Impact pad test
---------------------	----------------	-----------------

<b>Result</b>	<b>POSITIVE</b>	<b>POSITIVE</b>
<b>Place</b>	<b>Villeneuve</b>	<b>Villeneuve</b>
<b>Date</b>	<b>24.01.2022</b>	<b>10.08.2022</b>

## Issue data

**Place of declaration:** Villeneuve  
**Date of issue:** 11.10.2022  
**Managing Director:** Andrea Wigger  
**Signature:**


**Revision 01 : 06.12.2022**
**This revision cancels and replaces the previous one.**

"This inspection certificate is NOT covered by accreditation D-IS-19457-01."

This signature approve the validity of the test reports if available; no. 94.21b (test id 01,03,05,06,08,09,10,11,12,14,RRDT,RRST) and no. 94.22 (test id: P,PR) Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:

European Standard **EN1651:2018** and **EN12491:2015**

<sup>(1)</sup> If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismounted from the harness, e.g. airbag.

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22