



Harness inspection certificate

Inspection certificate number: PH_271.2019

Impact pad number: n/a


Manufacturer data

Manufacturer name: **DLCO**
 Representative: **Thomas Bourdeau**
 Street: **Le villaret**
 Post code / place: **05120 ST MARTIN DE QUEYRIERES**
 Country: **France**

Sample data:	Harness	Impact pad
Name:	Butterfly	Name Impact pad: ⁽¹⁾ n/a
Type:	ABS	Impact pad integrated: ⁽¹⁾ No
Size:	Unique	Impact pad type: n/a
Weight of Sample [kg]:	0.303	Weight of Sample [kg]: ⁽¹⁾ n/a
Serial number:	001	Serial number: ⁽¹⁾ n/a
Clip-in weight [kg]:	100	
Integrated container for rescue system:	n/a	Date of reception: n/a
Volume container [cm ³]:		n/a max n/a min
Date of reception:	12.04.2019	

Test report summary	Structual test	Impact pad test
Result	POSITIVE	n/a
Place	Villeneuve	n/a
Date	16.04.2019	n/a

Issue data

Place of declaration: **Villeneuve**
 Date of issue: **14.06.2019**
 Managing Director: **Alain Zoller**
 Signature: 

This signature approve the validity of the test reports if available; no. 94.21 (test id R0,R2,R6,R8,R9,R10,RRDT,RRST) and no. 94.22 (test id: P1,P2,PR1,PR2)

Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:

European Standard **EN1651 :1999**, and **EN12491:2015 chapter 5.3.2**

⁽¹⁾ If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismounted from the harness, e.g. airbag.

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22